

# CERTIFICATE

## ISO 9001:2015

DEKRA Certification SAS certifies that

# ANTAVIA

**Scope of certification:**

Provision of comprehensive maintenance and overhaul services: electro mechanics, hydraulics, power generation, electronics, landing gear, wheels and brakes, cabin equipment, rewinding, trading. Non-destructive testing: magnetic particle testing, penetrant testing, eddy current testing.

**Certified location:**

15 rue Sépat – 82370 CAMPSAS - France

has established and maintains a quality management system according to the aforementioned Standard. The conformity is demonstrated in the audit report no. 21-09-0538 rév1.

This certificate is valid from 29/05/2022 to 28/05/2025

Certificate registration no: 22-05-198

Date of re -/certification audit : 15/03/2022

  
Yvan MAINGUY  
Managing Director  
Le Plessis-Robinson, 25/05/2022



Lack of fulfilment on conditions as set out in the Certification Agreement may render this certificate invalid



# Annex to certificate N°22-05-198

Valid from 29/05/2022 until 28/05/2025

The following locations are covered by the certificate referenced above:

|           | <b>Subsidiaries / Sales offices</b><br><i>Filiales / Sites</i> | <b>Certified locations</b><br><i>Sites certifiés</i>        | <b>Scope of certification</b><br><i>Domaines certifiés</i>   |
|-----------|--|---|--|
| Main site | ANTAVIA  | 15 rue Sépat<br>82370 CAMPSAS<br>France                     | Provision of comprehensive maintenance and overhaul services: electro mechanics, hydraulics, power generation, electronics, landing gear, wheels and brakes, cabin equipment, rewinding, trading. Non-destructive testing: magnetic particle testing, penetrant testing, eddy current testing. |
| 1.        | ANTAVIA  | 11 rue de la Grande Borne, LE MESNIL-AMELOT 77990<br>France | Comprehensive maintenance and overhaul of aircraft wheels and brakes.<br>Non-destructive testing: magnetic particle testing, penetrant testing, eddy current testing   |

Lack of fulfilment on conditions as set out in the Certification Agreement may render this certificate invalid